

Annexure 01

REPAIR OF TILES AND ELECTRICAL SYSTEM IN OFFICE BUILDING AT DEVISIONAL SECRETARIAT OFFICE THISSAMAHARAMA

Weightings Of Inputs

Indices No.	Input Name	Input Percentage
M4	Cement	1.32%
M8	Sand	0.70%
M26	Electrical Wires	11.07%
M27	Wall Paint	8.20%
M38	Electrical Fittings	7.90%
L1	Skilled Labour	35.28%
L3	Unskilled Labour	25.53%
Total		90.00%

Non Ajustable Elements shall be:

BOQ Item Numbers:

1,2,3,12,20,51